

JF
DPD - 4002-39
COPY / OF /

June 8, 1959

Dear Dan:

There is a constantly increasing load of materials we must store in a vault whenever we lock up at night. These materials, of course, include all negative mission work and all reproductions in a partially completed state or awaiting shipment. In addition they include the Red Dot test material which are still valuable and are constantly being referred to and much test and quality control material needed for reference.

Our present vaults are crammed.

We have within our area a fair sized room with a concrete floor and ceiling and with substantial brick walls that can be made into a vault by bricking up one doorway and modifying another door to accept a new vault door (which would have to be purchased).

The estimate for this work is \$1225 without an air conditioner and \$2630 with an air conditioner. While the room is an internal one, the heat loads through the floor and ceiling are such that I am afraid we will have to provide some cooling.

We would like permission to do this work against
PO-660.

ELG/MDG
cc: J.L.B.
F.G.F.

E. L. G.

DOCUMENT NO. 266
NO CHANGE IN CLASS.
 DECLASSIFIED
CLASS. CHANGED TO: TS S.C. O 2011
NEXT PUBLISH DATE:
AUG 19 1972
DATE 07/24/91 REVIEWER 010956